



Approximate spill location. Excavations have been backfilled.



Trash is visible on fence adjacent to spill location.



Trash is visible at apparent backfilled excavation location/former working surface.



WGS84
±16ft

40.14554, -104.90687

m
±4m

1509

°T
±10

W277



CR17 & CR22 (N-2-3)
© 25-Feb-25 09:23:53 AM
ECMC Environmental Inspection