

Inspection Photos
Location Name: Brophy, M. 5-25
API Number: 125-08958



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Brophy, M. 5-25
API Number: 125-08958



3. View of unseated stuffing box.




4. Well location overview.

Inspection Photos
Location Name: Brophy, M. 5-25
API Number: 125-08958



5. Lease sign at gathering location.



6. Gas meter inside meter shed.