

## Inspection Photos

Location Name: MORO FARMS NE/4 SEC 29 TANK BATTERY 31-29, CNE-29

Location ID: 419648



Photo 1: Tank Battery sign. Not legible

Photo 2: Tank Battery sign. Not legible.





## Inspection Photos

Location Name: MORO FARMS NE/4 SEC 29 TANK BATTERY 31-29, CNE-29

Location ID: 419648



Photo 3: Tank battery sign. Not legible.



Photo 4: Dead vegetation and debris



## Inspection Photos

Location Name: MORO FARMS NE/4 SEC 29 TANK BATTERY 31-29, CNE-29

Location ID: 419648



Photo 5: Tank Battery. Dead vegetation and debris



Photo 6: Dead vegetation and debris



## Inspection Photos

Location Name: MORO FARMS NE/4 SEC 29 TANK BATTERY 31-29, CNE-29

Location ID: 419648



Photo 7: Dead vegetation and debris



Photo 8: Dead vegetation and debris



## Inspection Photos

Location Name: MORO FARMS NE/4 SEC 29 TANK BATTERY 31-29, CNE-29

Location ID: 419648



**Photo 9: Dead vegetation and debris**

