

# Inspection Photos

03/7/2025

**Operator:** LARAMIE ENERGY LLC #10433

**Location ID:** 436835

**Inspection Doc:** 718100295

Garfield County, CO

Aaron Trujillo  
Western Reclamation Work Lead  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 436835



**Photo 1:** Photos 1-2 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 436835



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 436835



March 7, 2025



March 7, 2025

**Photo 3:** Photos taken from the southern end of the Location. Photos examples showing Undesirable Plant Species (Halogeton) established on the working pad surface. Weed management efforts required to comply with Rule 606.c



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 436835



**Photo 4:** Photos taken from the interim areas on the west end of the Location. Photo example of areas throughout most if the interim that are progressing towards ECMC 1003 uniform standards.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 436835



**Photo 5:** Photos 5-6 taken from the northern and southern interim areas of the Location. Photos examples of areas where desirable, perennial vegetative establishment is not occurring in a uniform manner. Additional reclamation efforts, such as interseeding, required within these areas.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 436835



**Photo 6:** See comments under photo 5.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 436835



**Photo 7:** Photos taken from the methanol tank on the west end of the well string. Photo shows that a cap missing from containment BMP; Cap requires replacement to prevent wildlife access, such as birds, to the containment BMP



## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 436835



**Photo 8:** Photo taken from the second tank along the well string. Photo shows equipment appears to be leaking, as dark fluids beneath the equipment and on the wooden platform are evident.