

Final Reclamation and Stormwater Inspection

February 24, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 318195

Location Name: GRANT #2

Inspection Document #: 718600324

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: GRANT #2
Location ID: 318195



Photo 1. Looking south east across well location. Reclamation or site stabilization has not been performed. Gravel remains on location.



Photo 2. Looking east from wellbore. See Photo 1 comments.



Inspection Photos
Location Name: GRANT #2
Location ID: 318195



Photo 3. Looking west from wellbore. See Photo 1 comments.



Photo 4. Southwest corner of location. Electrical box remains on location.



Inspection Photos
Location Name: GRANT #2
Location ID: 318195



Photo 5. Looking northwest across location. See photo 1 comments.



Photo 6. Looking west across location. Soil is not stabilized, erosion channels are beginning to form.

