

Final Reclamation and Stormwater Inspection

January 27, 2025

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 330344

Location Name: BARB LTD #30-10

Inspection Document #: 718600345

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: BARB LTD #30-10
Location ID: 330344



Photo 1. Looking west down access road towards well location. Note the difference in vegetation color where the former access road and well were located.



Photo 2. Looking east from well location. Under the grey plant litter the location and access road are primarily covered with what appears to be Blue Mustard (*Chorispora tenella*) a non-native plant which was not observed in the reference area.



Inspection Photos
Location Name: BARB LTD #30-10
Location ID: 330344



Photo 3. Looking south from wellbore. No oil and gas equipment remains on location.



Photo 4. Looking west from wellbore. See photo 2 comments.



Inspection Photos
Location Name: BARB LTD #30-10
Location ID: 330344



Photo 5. Looking north from west side of location. This area appears to have desirable vegetation establishment.



Photo 6. Groundcover at wellbore. Appears to be Blue Mustard rosettes. Ground is densely covered with little plant diversity at the time of inspection.



Inspection Photos
Location Name: BARB LTD #30-10
Location ID: 330344



Photo 7. Last years flower stalk and seed pods.



Photo 8. Reference vegetation to the west of the location.

