

# Final Reclamation and Stormwater Inspection

March 4, 2025

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 323697

Well Name: EAST RINN H UNIT #1

Inspection Document #: 718600348

Weld County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: EAST RINN H UNIT #1  
Location ID: 323697



**Photo 1.** Picture taken looking east down former access road. Road has been converted to walking path.



**Photo 2.** Looking east across tank battery and wellbore. No oil and gas equipment remains.

Inspection Photos  
Location Name: EAST RINN H UNIT #1  
Location ID: 323697



**Photo 3.** Looking west from the wellbore. It appears that desirable vegetation has established and vegetation is reflective of the reference area.



**Photo 4.** Looking north from wellbore. See photo 3 comments.



Inspection Photos  
Location Name: EAST RINN H UNIT #1  
Location ID: 323697



Photo 5. Looking east from wellbore. See photo 3 comments.



Photo 6. Looking south from wellbore. See photo 3 comments.



Inspection Photos  
Location Name: EAST RINNH UNIT #1  
Location ID: 323697



Photo 7. Reference vegetation to the northwest of location.

