

# Final Reclamation and Stormwater Inspection

March 4, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 333243

Well Name: OLANDER #U 14-11

Inspection Document #: 718600350

Weld County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: OLANDER #U 14-11  
Location ID: 333243



**Photo 1.** Access road and culvert remain in place.



**Photo 2.** Looking north at the end of access road. Main access road appears to be a secondary exit from nearby warehouse (leads to gate). Well location and part of the access road appear to have reclamation work conducted.



Inspection Photos  
Location Name: OLANDER #U 14-11  
Location ID: 333243



**Photo 3.** Looking north across well location. No oil and gas equipment remains. Straw is present on location. At the time of inspection there was no germination or established desirable vegetation. Undesirable weeds Russian Thistle and Kochia were present on location. Location was primarily bare soil.



**Photo 4.** Looking west from center point between wellbores. see photo 3 comments.



Inspection Photos  
Location Name: OLANDER #U 14-11  
Location ID: 333243



**Photo 5.** Looking south from center point between wellbores.  
see photo 3 comments.



**Photo 6.** Looking east from center point between wellbores.  
see photo 3 comments.



Inspection Photos  
Location Name: OLANDER #U 14-11  
Location ID: 333243



**Photo 7.** Looking north from center point between wellbores.  
see photo 3 comments.



**Photo 8.** Reference vegetation to the east of location.

