

Final Reclamation and Stormwater Inspection

March 6, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 422691

Location Name: WARNER W/13-11 TANK

Inspection Document #: 718600362

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: WARNER W/13-11 TANK

Location ID: 422691



Photo 1. Looking west towards the former tank battery. Appears reclamation work has been performed on the access road.



Photo 2. Photo taken at the eastern end of access road. Appears some desirable vegetation has established, less than 80% of reference area.



Inspection Photos
Location Name: WARNER W/13-11 TANK
Location ID: 422691



Photo 3. Looking northwest over former tank battery from the south corner. No oil and gas equipment remains. It appears that reclamation work was performed with desirable vegetation establishment. Vegetation cover appears to be less than 80% of reference area and some bare soil patches are present.



Photo 4. Looking northwest from west side of tank battery towards well RLW W #13-12JI. Bare patches of soil.



Inspection Photos
Location Name: WARNER W/13-11 TANK
Location ID: 422691



Photo 5. Looking east across tank battery.



Photo 6. Reference vegetation to the south of tank battery.

