

Final Reclamation and Stormwater Inspection

March 6, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 309874

Well Name: WARNER W #13-24

Inspection Document #: 718600373

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: WARNER W #13-24
Location ID: 309874



Photo 1. Looking east down the access road from well UPRC #13-110. Some vegetation has established but there appears to be less than 80% coverage with bare dirt patches.



Photo 2. Looking east across location and access road. No oil and gas equipment remains. bare patches and lower vegetation coverage appear to be concentrated on the former access road and interim wellbore area.



Inspection Photos
Location Name: WARNER W #13-24
Location ID: 309874



Photo 3. Looking north from wellbore from the wellbore. Some vegetation has established but there appears to be less than 80% coverage with bare dirt patches.



Photo 4. Looking east from the wellbore. See photo 3 comments.



Inspection Photos
Location Name: WARNER W #13-24
Location ID: 309874



Photo 5. Looking south from wellbore. The southern side of the location appears to be progressing towards 80% of reference area.



Photo 6. Looking west from wellbore. See photo 5 comments.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 718600373

Inspection Photos
Location Name: WARNER W #13-24
Location ID: 309874



Photo 7. Reference vegetation to the northwest of the well location.