

Final Reclamation and Stormwater Inspection

March 6, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 422677

Well Name: WARNER W #13-11

Inspection Document #: 718600375

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: WARNER W #13-11
Location ID: 422677



Photo 1. Looking northeast across entrance to access road and reclaimed area next to it. Vegetation has established here but there appears to be less than 80% coverage.



Photo 2. Looking down the former access road. Vegetation appears to be less than 80% of reference area.



Inspection Photos
Location Name: WARNER W #13-11
Location ID: 422677



Photo 3. Looking east across well location. No oil and gas equipment remains. Some vegetation has established but it appears to be less than 80% coverage compared to the reference area.



Photo 4. Looking east from the wellbore. See photo 3 comments.



Inspection Photos
Location Name: WARNER W #13-11
Location ID: 422677



Photo 5. Looking north from wellbore. See photo 3 comments.



Photo 6. Looking west from wellbore. See photo 3 comments.



Inspection Photos
Location Name: WARNER W #13-11
Location ID: 422677



Photo 7. Looking south from wellbore. See photo 3 comments.



Photo 8. Reference vegetation to the south of the well location.

