

# Inspection Photos

March 12th, 2025

Operator: Simcoe LLC - 10749

Location ID: 326090

Inspection Document #: 714001948

La Plata County, CO

Township: NWSE 12 33N 10W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Elmer Dunkel A1  
Location ID: 326090



**Photo 1.** View of well pad taken from the access point facing center. Note: Location sign is missing from frame.





Inspection Photos  
Location Name: Elmer Dunkel A1  
Location ID: 326090



**Photo 2.** Sound panels have been reinstalled at the pump jack.



Inspection Photos  
Location Name: Elmer Dunkel A1  
Location ID: 326090

3/12/25  
227° SW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Weedy kochia debris remain lining the western edge of the pad.

API #: 067-07455



Inspection Photos  
Location Name: Elmer Dunkel A1  
Location ID: 326090



**Photo 4.** Stained soils remain at the wellhead.

