

Inspection Photos

March 12th, 2025

Operator: Simcoe LLC - 10749

Location ID: 333535

Inspection Document #: 714001950

La Plata County, CO

Township: SENW 18 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Alva Short B1
Location ID: 333535



3/12/25
330° NW



Photo 1. View of well pad taken from the access point facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07129

Inspection Photos
Location Name: Alva Short B1
Location ID: 333535



Photo 2. Labels at separators are deteriorating and no longer legible.

Inspection Photos
Location Name: Alva Short B1
Location ID: 333535



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Stained soils at wellhead have been removed. Combustible material are encroaching on wellhead.

API #: 067-07129