

# Inspection Photos

March 12th, 2025

Operator: Simcoe LLC - 10749

Location ID: 326680

Inspection Document #: 714001952

La Plata County, CO

Township: SENW 8 33N 9W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos  
Location Name: Clovis B2  
Location ID: 326680



Photo 1. View of wellhead assembly and location sign.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-08680



Inspection Photos  
Location Name: Clovis B2  
Location ID: 326680



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** Unmarked guyline anchor.

API #: 067-08680



Inspection Photos  
Location Name: Clovis B2  
Location ID: 326680



**Photo 3.** Separator equipment labels have deteriorated and are no longer legible.



Inspection Photos  
Location Name: Clovis B2  
Location ID: 326680



3/12/25  
14° N



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Surface owner equipment was not observed during this inspection.

API #: 067-08680