

Inspection Photos

March 12th, 2025

Operator: Simcoe LLC - 10749

Location ID: 306794

Inspection Document #: 714001953

La Plata County, CO

Township: SWNW 9 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: FC Southern Ute COM 005
Location ID: 306794



Photo 1. View of well location taken from the access point facing center. Note: location sign is bend and falling off frame.



Inspection Photos
Location Name: FC Southern Ute COM 005
Location ID: 306794



Photo 2. No stained soils observed at pump jack muffler.



Inspection Photos
Location Name: FC Southern Ute COM 005
Location ID: 306794

