

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF CLOUGH 19 Pad

Location ID: 322456



Photo # 2288 From entrance to location



Photo # 2289 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF CLOUGH 19 Pad

Location ID: 322456



Photo # 2290 Location



Photo # 2291 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF CLOUGH 19 Pad

Location ID: 322456



Photo # 2292 Location



Photo # 2293 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF CLOUGH 19 Pad

Location ID: 322456




Photo # 2294 Tank capacity incorrect




Photo # 2295 Tank capacity

