

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 205-20 Pad

Location ID: 324057



Photo # 4326 From entrance to location



Photo # 4327 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 205-20 Pad

Location ID: 324057



Photo # 4328 Location



Photo # 4329 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 205-20 Pad

Location ID: 324057



Photo # 4330 Location

Photo # 4331 Stored tank on location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 205-20 Pad

Location ID: 324057



Photo # 4332 Unsecured flange/wildlife hazard/available for entry by wildlife



Photo # 4333 Unsecured flange/wildlife hazard/available for entry by wildlife

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 205-20 Pad

Location ID: 324057



**Photo # 4334 Unsecured tank flange/wildlife hazard
/available for entry by wildlife**



**Photo # 4335 Unsecured tank flange/wildlife hazard
/available for entry by wildlife**

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 205-20 Pad

Location ID: 324057



**Photo # 4336 Unsecured tank flange/wildlife hazard
/available for entry by wildlife**



**Photo # 4337 Multiple unsecured openings on tank/wildlife
hazards/available for entry by wildlife**

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 205-20 Pad

Location ID: 324057



**Photo # 4338 Unsecured opening on tank/wildlife hazard
/available for entry by wildlife**



**Photo # 4339 Unsecured opening on tank/wildlife hazard
/available for entry by wildlife**

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 205-20 Pad

Location ID: 324057



**Photo # 4340 Unsecured opening on tank/wildlife hazard
/available for entry by wildlife**



**Photo # 4341 Unsecured opening on tank/wildlife hazard
/available for entry by wildlife**

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 205-20 Pad

Location ID: 324057



**Photo # 4342 Unsecured opening on tank/wildlife hazard
/available for entry by wildlife**