

Inspection Photos
Location Name: White Star Farms 5-22
API Number: 125-07513



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: White Star Farms 5-22
API Number: 125-07513




3. View of debris inside well fencing.



4. Well location overview.

Inspection Photos
Location Name: White Star Farms 5-22
API Number: 125-07513



5. Lease sign at gathering location.



6. Gathering location overview.