

Inspection Photos
Location Name: Lebsock 14-22 4N47W
API Number: 125-10616



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Lebsock 14-22 4N47W
API Number: 125-10616



3. Well location overview.



4. Lease sign at gathering location.

Inspection Photos
Location Name: Lebsock 14-22 4N47W
API Number: 125-10616



5. Gas meter inside meter shed.



6. Gathering location overview.