

Inspection Photos
Location Name: Serafini 'B' #3
API # 05-123-13579



Sign



Location

Inspection Photos
Location Name: Serafini 'B' #3
API # 05-123-13579




Well & Overgrown Vegetation



Overgrown Vegetation

Inspection Photos
Location Name: Serafini 'B' #3
API # 05-123-13579



Overgrown Vegetation



Valve appears to be shut in

Inspection Photos
Location Name: Serafini 'B' #3
API # 05-123-13579



March 17, 2025 at 9:58 AM
+40.1084, -105.0152
43° NE
Weld County
Energy & Carbon Management Commission

Valve appears to be shut in



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources