

**KT Resources LLC
Ant Hill Unit 29-13
Location ID: 316307**




When replaced additional information is required



Broken cap



KT Resources LLC
Ant Hill Unit 29-13
Location ID: 316307



Calibration overdue



Location from South entrance

**KT Resources LLC
Ant Hill Unit 29-13
Location ID: 316307**



Location from Northwest corner



Location from Northeast corner

