

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/16/2025

Submitted Date:

03/11/2025

Document Number:

710100363

FIELD INSPECTION FORMLoc ID 318062 Inspector Name: Anderson, Laurel On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kiel, Macy	970-515-1110	Macy_Kiel@oxy.com	Staff Environmental Engineer
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
318062	LOCATION	CL			-	WARNER TANK BATTERY 33-18	EI
442128	TANK BATTERY	CL	06/17/2015		-	WARNER TANK BATTERY 33-18	EI
482501	SPILL OR RELEASE	CL			-	Warner 11-18 Flowline	EI
483944	SPILL OR RELEASE	CL	02/16/2023		-	Warner 5&6&11/Muse EU O SA TB	EI
483946	SPILL OR RELEASE	CL			-	Warner 14-18 Flowline	EI

General Comment:

ECMC environmental inspection to determine progress on:
Spill ID 483944 (Closed under REM 26345; Date of Discovery: 2/13/2023)
Spill ID 483945 (Closed under REM 26349; Date of Discovery: 2/14/2023)
Spill ID 483946 (Closed under REM 26345; Date of Discovery: 2/16/2023)
Remediation Project #26345
Remediation Project #26349

Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Incident information:

Remediation #26345

Spill ID 483944 (Closed under REM 26345; Date of Discovery: 2/13/2023)

Days since spill discovery: 392 days as of 3/11/2025

Spill ID 483946 (Closed under REM 26345; Date of Discovery: 2/16/2023)

Days since spill discovery: 389 days as of 3/11/2025

Last report: Form 27s Doc #403437691 submitted on 09/10/2024 was denied on 11/19/2024

Remediation Project #26349

Spill ID 483945 (Closed under REM 26349; Date of Discovery: 2/14/2023)

Days since spill discovery: 391 days as of 3/11/2025

Last report: Form 27s Doc #403941439 submitted on 11/19/2024 was approved on 01/09/2025

Operator is past due on quarterly reporting (90 days) for both Remediation Projects.

Current site status: All equipment has been removed from the location with the exception of a 3rd party meter shed.

Environmental		
Spill/Remediation:		
Comment:	Remediation Project #26345 & Remediation Project #26349 are past due on quarterly (90 day) reporting.	
Corrective Action:	In accordance with Rule 913.e.(3), quarterly reporting (90 days) is required for Remediation Projects. CA due date back dated to when the Supplemental Form 27 for Remediation Project #26349 was due.	Date: 02/17/2025
Emission Control Burner (ECB): _____		
Comment: _____		
Pilot: _____ Wildlife Protection Devices (fired vessels): _____		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404122453	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6953805
710100364	2025_0306_REM 26345 & REM 26349_Photo Documentation	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6953803