

**Operator:** CRESTONE PEAK RESOURCES OPERATING LLC

**Location Name:** URSULA-62N66W/28NENE

**Loc ID:** 333219

**Inspection:** 717100085

**CA:** Trash observed on location. Comply with Rule 606.

**CA Resolution:** Operator has reported that trash has been removed, in order to comply with ECMC Rule 606.

**CA:** Riser observed missing OOSLAT. Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.

**CA Resolution:** Operator has reported that proper flowline abandonment has been completed in order to comply with ECMC Rule 1105

**CA:** Remediation Project No. 37471 was created for the plugging and abandonment of the Maier 1 wellhead and the removal of the associated flowline. Stockpiles associated with the release have been removed. No environmental impacts were visible. Quarterly reporting is required under Remediation Project No. 37471. Remediation Project No. 37481 was created for the decommissioning of the Ursula-62N66W 28NENE facility. Excavations have been backfilled. No environmental impacts were visible. Quarterly reporting was required under Remediation Project No. 37481; the last Form 27 for this project was submitted 10/07/2024 (Document No. 403946342). In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide an updated Form 27 for Remediation Project No.37481.

**CA Resolution:** Operator has submitted Form 27 Doc# 403998830 in order to comply with ECMC Rule 913.e.(3).