

# Inspection Photos

Loc: 309060

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 3/17/2025

County: LAS ANIMAS



## Inspection Photos



**Photo 1.** Facing west along the access road. BMP's are installed and in good condition along the road.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:309060 | Date: 3/17/2025

## Inspection Photos



**Photo 2.** Facing southwest further along the access road. BMP's are installed and in good condition along the road.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:309060 | Date: 3/17/2025

## Inspection Photos



**Photo 3.** Facing south west further along the access road. BMP's are installed and in good condition along the road.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:309060 | Date: 3/17/2025

Inspection Photos



**Photo 4.** Facing north along the access road toward the location.



Inspection Photos



**Photo 5.** Facing north toward the location.



Inspection Photos



**Photo 6.** Facing west along the fil slope which is stabilized with perennial vegetation.



Inspection Photos



**Photo 7.** Facing east at the location.



Inspection Photos



**Photo 8.** Facing southeast along the cut slope which is stabilized with perennial vegetation.



## Inspection Photos



**Photo 9.** Facing south at the location. Perennial vegetation is established throughout the location. No stormwater issues or noxious weeds were observed.

