

Inspection Photos

Loc: 308536

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 3/17/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308536 | Date: 3/17/2025

Inspection Photos



Photo 2. Facing southwest along the fill slope.



Inspection Photos



Photo 3. There is oil staining under the engine skid and at the wellhead that needs to be cleaned up.



Inspection Photos



Photo 4. Facing toward the produced water pit.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308536 | Date: 3/17/2025

Inspection Photos



Photo 5. There are two holes in the liner and the water level is right at the first hole shown at red arrow.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308536 | Date: 3/17/2025