

Inspection Photos

Loc: 307595

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 3/17/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast along the access road toward the wellsite.



Inspection Photos



Photo 2. Facing southwest toward the produced water pit.



Inspection Photos



Photo 3. Facing west along the access road traveling east from the wellsite. This area along the road side has eroded and will need BMP's such as check dams, culverts, ect. to further prevent erosion.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:307595 | Date: 3/17/2025

Inspection Photos



Photo 4. Facing east further along the road. This area has eroded and will need to be repaired and stabilized. Red arrow points to 4.5 ft shovel in the erosion gully.



Inspection Photos



Photo 5. Facing north toward the fill slope of the road. This area has eroded and will need to be repaired and stabilized.



Inspection Photos



Photo 6. Facing back south at the same area as the previous photo. This area has eroded and will need to be repaired and stabilized.

