

Inspection Photos

Loc: 307617

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 3/17/2025

County: LAS ANIMAS



Inspection Photos



Photo 1. Facing southeast along the access road toward the wellsite.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:307617 | Date: 3/17/2025

Inspection Photos



Photo 2. Facing southeast toward the wellsite.



Inspection Photos



Photo 3. Facing toward the produced water pit.



Inspection Photos



Photo 4. Facing west along the fil slope.

