

Final Reclamation Inspection

March 10, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 320330

Inspection Document #: 718800032

Adams County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MCKAY LAKE "F" UNIT 1
Location ID: 320330



Photo 1. Photo taken from the well location, facing North.
Photo illustrates the well location meets Rule 1004 standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: MCKAY LAKE "F" UNIT 1
Location ID: 320330



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: MCKAY LAKE "F" UNIT 1
Location ID: 320330



Photo 5. Photo taken from the well location access road, facing Southeast. Photo illustrates that the access road has been reclaimed and meets Rule 1004 standards.

