

# Final Reclamation Inspection

March 10, 2025

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 321357

Inspection Document #: 718800040

Boulder County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: LILEY #1-13  
Location ID: 321357



**Photo 1.** Photo taken from the access road, facing West toward the gate at the entrance to the location. Photo illustrates the access road meets Rule 1004 standards.



**Photo 2.** Photo taken from the well access road, facing Northeast. See comments under Photo 1.



Inspection Photos  
Location Name: LILEY #1-13  
Location ID: 321357



**Photo 3.** Photo taken from the access road, facing West toward the gate. See comments under Photo 1.



**Photo 4.** Photo taken from the well access road, facing North. See comments under Photo 1.



Inspection Photos  
Location Name: LILEY #1-13  
Location ID: 321357



**Photo 5.** Photo taken from the well location, facing North. Photo illustrates the well location meets Rule 1004 standards.



**Photo 6.** Photo taken from the well location, facing East. See comments under Photo 5.



Inspection Photos  
Location Name: LILEY #1-13  
Location ID: 321357



**Photo 7.** Photo taken from the well location, facing South. See comments under Photo 5.



**Photo 8.** Photo taken from the well location, facing West. See comments under Photo 5.