

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
404010004

Receive Date:  
\_\_\_\_\_

Report taken by:  
\_\_\_\_\_

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

|                                      |                                   |   |
|--------------------------------------|-----------------------------------|---|
| Name of Operator: NOBLE ENERGY INC   | Operator No: 100322               | Phone Numbers<br>Phone: (970) 939-1929<br>Mobile: ( ) |
| Address: 1099 18TH STREET SUITE 1500 |                                   |   |
| City: DENVER                         | State: CO                         | Zip: 80202  |
| Contact Person: Jason Davidson       | Email: jason.davidson@chevron.com |   |

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 34774 Initial Form 27 Document #: 403703684

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: \_\_\_\_\_

SITE INFORMATION

No Multiple Facilities

|  |                     |                        |  |
|--|---------------------|------------------------|--|
| Facility Type: WELL                            | Facility ID: _____  | API #: 123-17678       | County Name: WELD                          |
| Facility Name: TODD 20-2                       | Latitude: 40.302677 | Longitude: -104.571630 |  |
| ** correct Lat/Long if needed: Latitude: _____ |                     | Longitude: _____       |  |
| QtrQtr: NWNE                                   | Sec: 20             | Twps: 4N               | Range: 64W Meridian: 6 Sensitive Area? Yes |

SITE CONDITIONS

General soil type - USCS Classifications SW Most Sensitive Adjacent Land Use Grassland

Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? No

**Other Potential Receptors within 1/4 mile**

Freshwater Pond 0.18mi S  
Riverine 0.09/0.1mi E  
Residential 0.11/0.21/0.22mi N, 0.19/0.23mi NE  
Farm Structure 0.09/0.23/0.24mi N, 0.16/0.18/0.22mi NE, 0.25mi SE

# SITE INVESTIGATION PLAN

## **TYPE OF WASTE:**

- |  |  |  |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste      | <input type="checkbox"/> Other E&P Waste             | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids             | _____                                  |
| <input checked="" type="checkbox"/> Oil            | <input type="checkbox"/> Tank Bottoms                |  |
| <input checked="" type="checkbox"/> Condensate     | <input type="checkbox"/> Pigging Waste               |  |
| <input type="checkbox"/> Drilling Fluids           | <input type="checkbox"/> Rig Wash                    |  |
| <input type="checkbox"/> Drill Cuttings            | <input type="checkbox"/> Spent Filters               |  |
|  | <input type="checkbox"/> Pit Bottoms                 |  |
|  | <input type="checkbox"/> Other (as described by EPA) | _____                                  |

## **DESCRIPTION OF IMPACT**

| Impacted?    | Impacted Media | Extent of Impact                    | How Determined                                  |
|--------------|----------------|-------------------------------------|---|
| UNDETERMINED | GROUNDWATER    | NA                                  | Lab analysis or Field Screening, if encountered |
| Yes          | SOILS          | IOs only: Refer to Tables & Figures | Lab analysis and field screening                |

## **INITIAL ACTION SUMMARY**

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Pursuant to ECMC Rule 911 a site investigation was conducted pertaining to the TODD 20-02 wellhead cut and cap and flowline removal. Approximately 1058' of flowline was removed. The wellhead was cut and capped per ECMC rules. Additionally, soil samples were field screened at the N-E-S-W sides of the wellhead. Soil samples were also taken along the flowline any points of material change and/or hammer unions, directional changes, as well as at the bell holes on either side of a waterway.

## **PROPOSED SAMPLING PLAN**

### **Proposed Soil Sampling**

Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

A grab soil sample was collected at the base of the excavation or the area showing the highest degree of impact during field screening activities at the wellhead excavation. Additionally, soil samples were field screened at the N-E-S-W sides of the wellhead. Soil samples were taken along the flowline at any points of material change and/or hammer unions, directional changes, as well as at the bell holes on either side of a waterway. Soil samples were analyzed by a certified laboratory for the full extent of Table 915-1, including but not limited to: TPH (total volatile [C6-C10] and extractable [C10-C36] hydrocarbons) organic compounds in soil per ECMC Table 915-1, and EC, SAR, pH, metals, and boron. All samples collected were analyzed by a certified laboratory using approved ECMC laboratory analysis methods.

### **Proposed Groundwater Sampling**

Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

If groundwater is encountered during the site investigation a grab groundwater sample will be collected and analyzed for all organic compounds and inorganic parameters per ECMC Table 915-1.

### **Proposed Surface Water Sampling**

Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

## **Additional Investigative Actions**

Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

Visual inspection of the wellhead and flowline areas occurred during abandonment activities. Field personnel field screened all disturbed areas using visual and olfactory senses to determine if laboratory confirmation sampling was required. The ECMC Flowline Closure and Wellhead Closure Checklists was utilized and filled out during the abandonment process. A detailed summary of decommissioning activities, including field notes, site photos, figures, and laboratory analytical results, is attached to this Form 27.

# SITE INVESTIGATION REPORT

## **SAMPLE SUMMARY**

**Soil**

Number of soil samples collected 2  
Number of soil samples exceeding 915-1 2  
Was the areal and vertical extent of soil contamination delineated? No  
Approximate areal extent (square feet) 200

**NA / ND**

ND Highest concentration of TPH (mg/kg) \_\_\_\_\_  
-- Highest concentration of SAR 0.451  
BTEX > 915-1 No  
Vertical Extent > 915-1 (in feet) 6

**Groundwater**

Number of groundwater samples collected 0  
Was extent of groundwater contaminated delineated? Yes  
Depth to groundwater (below ground surface, in feet) \_\_\_\_\_  
Number of groundwater monitoring wells installed \_\_\_\_\_  
Number of groundwater samples exceeding 915-1 \_\_\_\_\_

Highest concentration of Benzene (µg/l) \_\_\_\_\_  
Highest concentration of Toluene (µg/l) \_\_\_\_\_  
Highest concentration of Ethylbenzene (µg/l) \_\_\_\_\_  
Highest concentration of Xylene (µg/l) \_\_\_\_\_  
Highest concentration of Methane (mg/l) \_\_\_\_\_

**Surface Water**

0 Number of surface water samples collected  
\_\_\_\_\_ Number of surface water samples exceeding 915-1  
If surface water is impacted, other agency notification may be required.

**OTHER INVESTIGATION INFORMATION**

Were impacts to adjacent property or offsite impacts identified?

\_\_\_\_\_

Were background samples collected as part of this site investigation?

\_\_\_\_\_

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) \_\_\_\_\_ Volume of liquid waste (barrels) \_\_\_\_\_

Is further site investigation required?

A supplemental site investigation (SSI) will be completed to collect additional background samples to determine if elevated levels of pH and arsenic are attributed to native soil conditions at the site. Proposed background sample locations are included in the attached Site Map. Background soil samples will be analyzed by a certified laboratory for analysis of metals per ECMC Table 915-1 and soil suitability parameters including pH, EC, SAR, and boron. The SSI will be completed in accordance with the proposed implementation schedule, and the results of the SSI will be submitted on a subsequent Form 27. The confirmation soil samples collected during wellhead cut and cap activities were determined to be outside of the required temperature preservation range when delivered to the laboratory. Re-sampling will be conducted.

**REMEDIAL ACTION PLAN**

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

**SOURCE REMOVAL SUMMARY**

Describe how source is to be removed.

No impacted material caused by oil and gas operations was identified at this time.

**REMEDICATION SUMMARY**

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

A supplemental site investigation (SSI) will be completed to collect additional background samples to determine if elevated levels of pH and arsenic are attributed to native soil conditions at the site. Proposed background sample locations are included in the attached Site Map. Background soil samples will be analyzed by a certified laboratory for analysis of metals per ECMC Table 915-1 and soil suitability parameters including pH, EC, SAR, and boron. The SSI will be completed in accordance with the proposed implementation schedule, and the results of the SSI will be submitted on a subsequent Form 27. The confirmation soil samples collected during wellhead cut and cap activities were determined to be outside of the required temperature preservation range when delivered to the laboratory. Re-sampling will be conducted.

**Soil Remediation Summary**

In Situ

- \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )
- \_\_\_\_\_ Chemical oxidation
- \_\_\_\_\_ Air sparge / Soil vapor extraction
- \_\_\_\_\_ Natural Attenuation
- \_\_\_\_\_ Other \_\_\_\_\_

Ex Situ

- \_\_\_\_\_ Excavate and offsite disposal
- \_\_\_\_\_ If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_
- \_\_\_\_\_ Name of Licensed Disposal Facility or ECMC Facility ID # \_\_\_\_\_
- \_\_\_\_\_ Excavate and onsite remediation
- \_\_\_\_\_ Land Treatment
- \_\_\_\_\_ Bioremediation (or enhanced bioremediation)
- \_\_\_\_\_ Chemical oxidation
- \_\_\_\_\_ Other \_\_\_\_\_

**Groundwater Remediation Summary**

- \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )
- \_\_\_\_\_ Chemical oxidation
- \_\_\_\_\_ Air sparge / Soil vapor extraction
- \_\_\_\_\_ Natural Attenuation
- \_\_\_\_\_ Other \_\_\_\_\_

**GROUNDWATER MONITORING**

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was not encountered during site investigation or excavation activities.

# REMEDIATION PROGRESS UPDATE

## PERIODIC REPORTING

### Approved Reporting Schedule:

Quarterly     Semi-Annually     Annually     Other

### Request Alternative Reporting Schedule:

Semi-Annually     Annually     Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type:     Groundwater Monitoring     Land Treatment Progress Report     O&M Report

Other Decommissioning Sample Summary & Supplemental Site Investigation Proposal

## Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Noble intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Noble has general liability insurance (policies MWZZ316714 and MWZX316724) and financial assurance in compliance with ECMC rules. Records are available on the ECMC's website. The cost for remediation is an estimate only, costs may change upwards or downward based on site-specific information. Noble makes no representation or guarantees as to the accuracy of the estimate.

Operator anticipates the remaining cost for this project to be: \$ 50000

## WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards

E&P waste (solid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

Volume of E&P Waste (liquid) in barrels

E&P waste (liquid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

## REMEDIATION COMPLETION REPORT

### REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

Compliant with Rule 913.h.(1).

Compliant with Rule 913.h.(2).

Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards?

Does the previous reply indicate consideration of background concentrations?

Does Groundwater meet Table 915-1 standards? \_\_\_\_\_

Is additional groundwater monitoring to be conducted? \_\_\_\_\_

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete? Yes \_\_\_\_\_

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim  Final

Did the Surface Owner provide the seed mix? \_\_\_\_\_

If YES, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

Did the local soil conservation district provide the seed mix? \_\_\_\_\_

### SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 05/17/2024

Proposed date of completion of Reclamation. 10/31/2026

## IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. 02/29/2024

Actual Spill or Release date, or date of discovery. \_\_\_\_\_

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 05/17/2024

Proposed site investigation commencement. 02/25/2025

Proposed completion of site investigation. 10/25/2025

### REMEDIAL ACTION DATES

Proposed start date of Remediation. 02/25/2025

Proposed date of completion of Remediation. 10/25/2025

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

The implementation schedule has been changed due to the decommissioning of the Todd 20-02 wellhead/flowline and necessity for supplemental site investigation activities adjacent to the wellhead/flowline. The proposed site investigation will be completed following the approval of this form.

**OPERATOR COMMENT**

This Form 27 is being submitted to include the decommissioning results at the former Todd 20-02 wellhead/flowline location. The WH sampling was conducted by Entrada Consulting in May 2024 and identified no organic exceedances. A secured analytical data report is attached and data summarized in the attached Entrada data package. In August 2024, Tasman conducted sampling activities along the flowline. Upon receipt of a secured laboratory report, analytical findings will be summarized and provided.

A supplemental site investigation (SSI) will be completed to collect additional background samples to determine if elevated levels of pH and arsenic are attributed to native soil conditions at the site. Proposed background sample locations are included in the attached Site Map. Background soil samples will be analyzed by a certified laboratory for analysis of metals per ECMC Table 915-1 and soil suitability parameters including pH, EC, SAR, and boron. The SSI will be completed in accordance with the proposed implementation schedule, and the results of the SSI will be submitted on a subsequent Form 27.

Background samples have not been collected yet due to frozen ground conditions. Background samples are tentatively planned for summer 2025 and will follow previously submitted proposed locations.

The confirmation soil samples collected during wellhead cut and cap activities were determined to be outside of the required temperature preservation range when delivered to the laboratory. Re-sampling will be conducted.

Quarterly reporting will be conducted until closure criteria are achieved for the remediation project. The results of the supplemental site investigation will be submitted on a subsequent Form 27.

In response to ECMC returning to draft Form 27 Document Number 404010004 on 1/27/2025, Operator is submitting a replacement Form 27. Based on currently available data, this project is not affected by data integrity irregularities and is not associated with Operator's data integrity review process and its Rule 525.e. Voluntary Disclosure. As part of its data integrity review process, Operator requested the lab protect the laboratory analytical reports from subsequent unauthorized modification by anyone outside the lab, which resulted in the lab reissuing the original report with additional protections (Reissued Report). The Reissued Report was received directly from the lab on 2/13/2025 which includes a watermark confirming both the laboratory representative who reissued the report and the date and time of the reissuance. The metadata associated with these Reissued Report also includes the lab representative's name, the date and time the laboratory reissued the report, and an explanation for the report reissuance. The Reissued Report is attached to this submission.

In the event additional responsive information is received or discovered that would suggest this project should be incorporated into the ongoing data integrity review process associated with Operator's Rule 525.e. Voluntary Disclosure, Operator will update and/or amend the statements in this submission and provide any new or revised data or other information.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Kayla White, P.E.

Title: Environmental Consultant

Submit Date: \_\_\_\_\_

Email: kwhite@cdhconsult.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: \_\_\_\_\_

Date: \_\_\_\_\_

Remediation Project Number: 34774

**COA Type**

**Description**

|       |  |
|-------|--|
| 0 COA |  |
|-------|--|

**ATTACHMENT LIST**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

| Att Doc Num | Name                      |
|-------------|---------------------------|
| 404011261   | SITE INVESTIGATION REPORT |
| 404017097   | SITE MAP                  |
| 404104558   | ANALYTICAL RESULTS        |

Total Attach: 3 Files

**General Comments**

| User Group | Comment | Comment Date        |
|------------|---------|---------------------|
|            |         | Stamp Upon Approval |

Total: 0 comment(s)