

Inspection Photos

March 18th, 2025

Operator: Simcoe LLC - 10749

Location ID: 312080

Inspection Document #: 714001979

La Plata County, CO

Township: SWNW 14 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Thomas Jacquez A1
Location ID: 312080



Photo 1. View of well pad taken from the access point facing center.

Inspection Photos
Location Name: Thomas Jacquez A1
Location ID: 312080




Photo 2. View of weedy kochia and russian thistle debris observed on the edge of the active pad.

Inspection Photos
Location Name: Thomas Jacquez A1
Location ID: 312080



Photo 3. Stained soils/gravel at wellhead have been removed.

Inspection Photos
Location Name: Thomas Jacquez A1
Location ID: 312080



Photo 4. Unused sign/trash observed along the access point to the location.