

Inspection Photos

March 18th, 2025

Operator: Simcoe LLC - 10749

Location ID: 326634

Inspection Document #: 714001980

La Plata County, CO

Township: NESW 14 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Thomas Jacquez A2
Location ID: 326634



Photo 1. View of well pad taken from the access point facing center.

Inspection Photos
Location Name: Thomas Jacquez A2
Location ID: 326634

3/18/25
274° W



Photo 2. Labels at separator equipment has deteriorated and is no longer legible.



Inspection Photos
Location Name: Thomas Jacquez A2
Location ID: 326634

