

Inspection/Audit Photos

Location Name: QB Energy FEDERAL K-2-7-94-S (RK2) Pad

Location #: 334992



Photo # 5601 From entrance to location





Photo # 5602 Location

Inspection/Audit Photos

Location Name: QB Energy FEDERAL K-2-7-94-S (RK2) Pad

Location #: 334992



Mar 19, 2025 at 4:45:06 PM

Photo # 5603 Location



Mar 19, 2025 at 4:46:44 PM

Photo # 5604 Location

Inspection/Audit Photos

Location Name: QB Energy FEDERAL K-2-7-94-S (RK2) Pad

Location #: 334992



Photo # 5605 Location



Photo # 5606 Location

Inspection/Audit Photos

Location Name: QB Energy FEDERAL K-2-7-94-S (RK2) Pad

Location #: 334992



**Photo # 5607 Burner assembly open ended/wildlife hazard
/available for entry by wildlife**



**Photo # 5608 Burner assembly open ended/wildlife hazard
/available for entry by wildlife**