

Inspection Photos
Location Name: Murrain M 3-30
API Number: 125-06838



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Murrain M 3-30
API Number: 125-06838



3. Well location overview.



4. Lease sign at gathering location.

Inspection Photos
Location Name: Murrain M 3-30
API Number: 125-06838



5. Damaged shed door with missing handle. Door is jammed and inspector unable to access.



6. Gas meter inside meter shed.

Inspection Photos
Location Name: Murrain M 3-30
API Number: 125-06838



7. Produced water tanks (30 BBL) each and Content/Quantity/Hazard sign reflects 200 BBL.



8. Tank labeled as 30 BBL.

Inspection Photos
Location Name: Murrain M 3-30
API Number: 125-06838



9. Additional production tank labeled as 30 BBL.



10. Gathering location overview.