

Inspection Photos
Location Name: Centex 16-25
Location ID: 336527



Photo 1 Location



Photo 2 ECD.

Inspection Photos
Location Name: Centex 16-25
Location ID: 336527



Photo 3 Horizontal heated separator.



Photo 4 Well site.

Inspection Photos
Location Name: Centex 16-25
Location ID: 336527



Photo 5 Wellhead sign.

Photo 6 Wellhead & sign.

Inspection Photos
Location Name: Centex 16-25
Location ID: 336527



Photo 7 Wellhead & sign.



Photo 8 Tank battery.

Inspection Photos
Location Name: Centex 16-25
Location ID: 336527




Photo 9 Tank battery & signs.