

Inspection Photos
Location Name: D & S 22-31 4N46W
API Number: 125-10095



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: D & S 22-31 4N46W
API Number: 125-10095



3. Well location overview.




4. Lease sign at gathering location.

Inspection Photos
Location Name: D & S 22-31 4N46W
API Number: 125-10095



5. Gas meter inside meter shed.



6. Gas meter Calibration/Test Log from inside meter shed.
Last recorded calibration was 3-3-23.