

Inspection Photos  
Location Name: Brophy T 50-31  
API Number: 125-07145



1. Lease sign at well location.



2. View of wellhead.



**Inspection Photos**  
**Location Name: Brophy T 50-31**  
**API Number: 125-07145**



**3. View of water line on wellhead tree with damp stained soil below check valve.**



**4. View of split in check valve body.**

Inspection Photos  
Location Name: Brophy T 50-31  
API Number: 125-07145



5. Lease sign at gathering location.



6. Gas meter inside meter shed.



**Inspection Photos**  
**Location Name: Brophy T 50-31**  
**API Number: 125-07145**

[illegible]

**7. Gas meter Calibration/Test Log from inside meter shed.  
Last recorder calibration 3-3-23.**



## 8. Gathering location overview.