

Final Reclamation and Stormwater Inspection

March 11, 2025

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 320215

Well Name: EDNA #1

Inspection Document #: 718600377

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: EDNA #1
Location ID: 320215



Photo 1. Looking east across the former tank battery and well location. Undesirable weed Kochia is present throughout the location. All oil and gas equipment has been removed from the well location.



Photo 2. Looking east across the tank battery. It appears that reclamation has been conducted with evidence of straw. There are large patches of bare soil with no desirable vegetation establishment.



Inspection Photos
Location Name: EDNA #1
Location ID: 320215



Photo 3. Looking west across the former tank battery. See photo 2 comments.



Photo 4. Looking east across the wellbore. It appears that reclamation has been conducted with evidence of straw. There is some desirable vegetation beginning to establish around the wellbore. Undesirable weed Kochia is present throughout the location.



Inspection Photos
Location Name: EDNA #1
Location ID: 320215



Photo 5. Looking south from wellbore. See photo 4 comments.



Photo 6. Looking west from wellbore. See photo 4 comments.



Inspection Photos
Location Name: EDNA #1
Location ID: 320215



Photo 7. Looking south from wellbore. See photo 4 comments.



Photo 8. Reference vegetation to the north of the well location.

