

Inspection/Audit Photos

Location Name: QB Energy ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Photo # 5375 From entrance to location



Photo # 5376 From entrance to location

Inspection/Audit Photos

Location Name: QB Energy ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Photo # 5377 Location

Photo # 5378 Location

Inspection/Audit Photos
Location Name: QB Energy ROSE RANCH 23-4D (A22W) Pad
Location #: 334755



Photo # 5379 Location



Photo # 5380 Location

Inspection/Audit Photos

Location Name: QB Energy ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Photo # 5381 Location



Photo # 5382 Location

Inspection/Audit Photos

Location Name: QB Energy ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Photo # 5383 Location



Photo # 5384 Location

Inspection/Audit Photos
Location Name: QB Energy ROSE RANCH 23-4D (A22W) Pad
Location #: 334755



Photo # 5385 Location

Photo # 5386 Location

Inspection/Audit Photos

Location Name: QB Energy ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Photo # 5387 Location



Photo # 5388 Location

Inspection/Audit Photos

Location Name: QB Energy ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Photo # 5389 Location



Photo # 5390 Location

Inspection/Audit Photos

Location Name: QB Energy ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Photo # 5391 Location



**Photo # 5392 Flowline heating insulation open ended
/wildlife hazard/available for entry by wildlife**

Inspection/Audit Photos

Location Name: QB Energy ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Photo # 5393 PRV vent line does not comply with CECMC pressure safety device rules




Photo # 5394 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: QB Energy ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



Photo # 5395 PRV vent line does not comply with CECMC pressure safety device rules




Photo # 5396 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: QB Energy ROSE RANCH 23-4D (A22W) Pad

Location #: 334755



**Photo # 5397 Flowline heating insulation open ended
/wildlife hazard/available for entry by wildlife**