



Inspection Photos
Location Name: Bryce Day 3-24
API Number: 125-09105



1. Lease sign at gathering location 01/14/2025.



2. Lease sign at gathering location 03/17/2025.

Inspection Photos
Location Name: Bryce Day 3-24
API Number: 125-09105



3. Separation equipment as seen 01/14/2025.



4. Separation equipment as seen 03/17/2025. Operator and contact information added. No associated well information.