

Inspection Photos
Location Name: Tuell Harry J 1
API Number: 125-06151



1. Lease sign at well location 01/16/2025.



1. Lease sign at well location 03/17/2025.

Inspection Photos
Location Name: Tuell Harry J 1
API Number: 125-06151



**3. View of wellhead. Note debris on ground inside shed
01/16/2025.**



4. Location overview 03/17/2025.

Inspection Photos
Location Name: Tuell Harry J 1
API Number: 125-06151



5. Separator/Well shed door 01/16/2025.



6. Separator/Well shed door 03/17/2025. Moved but not removed or repaired.

Inspection Photos
Location Name: Tuell Harry J 1
API Number: 125-06151



7. Old fencing piled on well location 01/16/2025.



8. Old fencing piled on well location 03/17/2025.