

Inspection Photos

Location Name: HELDT-66N64W/18SWNW

Location #: 330743




Photo #1

Heldt 12-18 (123-19549) Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: cement-squeeze



Photo #2

Heldt 12-18 Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: cement-squeeze

Site safety signage



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos Location Name: HELDT-66N64W/18SWNW Location #: 330743



Photo #3

Heldt 12-18 Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: cement-squeeze

Wellsite entrance




Photo #4

Heldt 12-18 Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: cement-squeeze

JSA: 2025-03-19



Inspection Photos

Location Name: HELDT-66N64W/18SWNW

Location #: 330743



Photo #5

Heldt 12-18 Battery site

Plugged & Abandoned | PA

Plugging Ops; Cementing: cement-squeeze

Battery sign



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources