

Inspection Photos

Location Name: HELDT-66N64W/18SWNW

Location #: 330743



Photo #1

Heldt 12-18 (123-19549) Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: surface base plug



Photo #2

Heldt 12-18 Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: surface base plug

Site safety signage

prior photo



COLORADO

**Energy & Carbon Management
Commission**


Department of Natural Resources

Inspection Photos Location Name: HELDT-66N64W/18SWNW Location #: 330743



Colorado Energy & Carbon Management Commission
Weld County
+40.487732, -104.581607
119° SE
2025-03-19 15:52

Photo #3
Heldt 12-18 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: surface base plug
Wellsite entrance
prior photo



Colorado Energy & Carbon Management Commission
Weld County
+40.487426, -104.599678
38° NE
2025-03-20 14:02

Photo #4
Heldt 12-18 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: surface base plug
JSA: 2025-03-20



Inspection Photos

Location Name: HELDT-66N64W/18SWNW

Location #: 330743



Photo #5

Heldt 12-18 Battery site

Plugged & Abandoned | PA

Plugging Ops; Cementing: surface base plug

Battery sign

prior photo



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources