

Inspection Photos  
Location Name: Eystone 5-35  
API Number: 125-08706



1. Lease sign at well location as seen 02/06/2025.



2. Lease sign at well location as seen 03/17/2025.

**Inspection Photos**  
**Location Name: Eyestone 5-35**  
**API Number: 125-08706**



**3. View of wellhead as seen 02/06/2025.**



**4. View of wellhead as seen 03/17/2025.**



**Inspection Photos**  
**Location Name: Eyestone 5-35**  
**API Number: 125-08706**



**5. View of release location at wellhead. Note absence of fine sand at release point as seen 02/06/2025.**



**6. View of release location at wellhead. Note absence of fine sand at release point as seen 03/17/2025.**

**Inspection Photos**  
**Location Name: Eyestone 5-35**  
**API Number: 125-08706**



**7. View of leaking check valve. Note salt staining on check valve body as seen 02/06/2025.**



**8. View of leaking check valve. Note salt staining on check valve body as seen 03/17/2025.**



**Inspection Photos**  
**Location Name: Eyestone 5-35**  
**API Number: 125-08706**



**9. View of leaking check valve. Note salt staining on check valve body as seen 03/17/2025.**



**10. Area directly below leaking check valve as seen 03/17/2025.**