

Inspection Photos
Location Name: RMR Ranch 2
API Number: 125-07290



1. Lease sign at well location as seen 01/15/2025.



2. Lease sign at well location as seen 03/17/2025.

Inspection Photos
Location Name: RMR Ranch 2
API Number: 125-07290



3. View of produced water tank at gathering location as seen 01/15/2025.



4. View of produced water tank at gathering location as seen 03/17/2025.

Inspection Photos
Location Name: RMR Ranch 2
API Number: 125-07290



5. Gathering location overview as seen 01/15/2025.



6. Gathering location overview as seen 03/17/2025.