

Inspection Photos
Location Name: SIMPSON A9
Location ID: 319940



Photo #1 Tanks.



Photo #2 Some rusting & stained soil around tanks.

Inspection Photos
Location Name: SIMPSON A9
Location ID: 319940



Photo #3 Some rusting & stained soil around tanks.



Photo #4 stained soil under valve

Inspection Photos
Location Name: SIMPSON A9
Location ID: 319940



Photo #5 P/W tank.



Photo #6 No lid on P/W tank.

Inspection Photos
Location Name: SIMPSON A9
Location ID: 319940



Photo #7 Pit .



Photo #8 Pit with some weeds starting to accumulate.

Inspection Photos
Location Name: SIMPSON A9
Location ID: 319940



Photo #9 Separators.



Photo #10 Pump Jack.

Inspection Photos
Location Name: SIMPSON A9
Location ID: 319940



Photo #11 Used pipe and unused equipment.



Photo #12 Buckets with oil in them.