

Final Reclamation Inspection

March 19, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 318197

Inspection Document #: 718800048

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CHAMPLIN 41-4 #1
Location ID: 318197




Photo 1. Google Earth aerial imagery from October 6, 2013. Photo illustrates the well location, access road, and associated tank battery during active operations.



Inspection Photos
Location Name: CHAMPLIN 41-4 #1
Location ID: 318197




Photo 2. Google Earth aerial imagery from May 22, 2023. Photo illustrates the well location, access road, and associated tank battery after plugging operations. Photo illustrates that the location is now contained within a land use change to residential development.

Inspection Photos
Location Name: CHAMPLIN 41-4 #1
Location ID: 318197



Photo 3. Photo taken from the well location, facing North. Photo illustrates that the well location is contained within a land use change from cropland to a residential development.



Photo 4. Photo taken from the well location, facing East. See comments under Photo 3.



Inspection Photos
Location Name: CHAMPLIN 41-4 #1
Location ID: 318197



Photo 5. Photo taken from the well location, facing South. See comments under Photo 3.



Photo 6. Photo taken from the well location, facing West. See comments under Photo 3.

