

# Final Reclamation Inspection

March 19, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 318198

Inspection Document #: 718800052

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC




**COLORADO**

**Energy & Carbon Management  
Commission**


Department of Natural Resources

Inspection Photos  
Location Name: CHAMPLIN 32-4 #2  
Location ID: 318198



**Photo 1.** Google Earth aerial imagery from October 7, 2012. Photo illustrates the well location and access road during active operations.

Inspection Photos  
Location Name: CHAMPLIN 32-4 #2  
Location ID: 318198



**Photo 2.** Google Earth aerial imagery from March 2, 2025. Photo illustrates the well location and access road after plugging operations. This imagery illustrates that the location disturbance is now contained within a land use change to a residential development.



Inspection Photos  
Location Name: CHAMPLIN 32-4 #2  
Location ID: 318198



**Photo 3.** Photo taken of the well location, facing South. Photo illustrates that the well location is contained within a land use change from cropland to a residential development.