

**KT Resources LLC
Ant Hill Unit 25-22
Location ID: 316260**



Incorrect well name and missing information



Valve left open

**KT Resources LLC
Ant Hill Unit 25-22
Location ID: 316260**



Leaking equipment and oily waste



Oily waste and staining

KT Resources LLC
Ant Hill Unit 25-22
Location ID: 316260



Missing required information

Mar 24, 2025 at 10:42:13 AM

Est. 5851' Rio Blanco

EMPACT ANALYTICAL SYSTEMS INC.
365 SOUTH MAIN
BRIGHTON, CO 80601
303-637-0150 www.empactanalytical.com

Meter S/N
15114130
C-9226

Station Name AHU 25-22
Station No. 120235552 Producer 31 OP
Sec 25 Township 2N Range 97W
Diff 256" Temp Range 0-150 Tube Size 3.868
Static 200# Absolute 11.84 psig
ORIFICE SS# 02086142 Donnell

	Date	Orifice Plate Size	Meter Test Date	Sample Date
6W	3-21-18	1.000	3-21-18	3-21-18
K8	9-19-18	1.000	9-19-18	9-19-18
7919	2-8-22	1.000	2-8-22	4-16-19
	3-19-25	1.000	Ty/Hughes	CA/100

K8

Contractor? Operator?



**KT Resources LLC
Ant Hill Unit 25-22
Location ID: 316260**



Erosion and sediment migration from location



Erosion and sediment migration from location

**KT Resources LLC
Ant Hill Unit 25-22
Location ID: 316260**



Erosion and sediment migration from location



Stormwater BMPs not maintained

**KT Resources LLC
Ant Hill Unit 25-22
Location ID: 316260**



Access road



Location from Northwest entrance

**KT Resources LLC
Ant Hill Unit 25-22
Location ID: 316260**



Location from East corner



Location from South corner