

**Inspection/Audit Photos**  
**Location Name: QB Energy COUEY 5-14 (N5) Pad**  
**Location #: 334963**



**Photo # 6604 From entrance to location**



**Photo # 6605 From entrance to location**

**Inspection/Audit Photos**  
**Location Name: QB Energy COUEY 5-14 (N5) Pad**  
**Location #: 334963**



**Photo # 6606 Location**



**Photo # 6607 Location**



**Inspection/Audit Photos**  
**Location Name: QB Energy COUEY 5-14 (N5) Pad**  
**Location #: 334963**



**Photo # 6608 Location**




**Photo # 6609 Location**



**Inspection/Audit Photos**  
**Location Name: QB Energy COUEY 5-14 (N5) Pad**  
**Location #: 334963**



**Photo # 6610 Location**



**Photo # 6611 Location**



**Inspection/Audit Photos**  
**Location Name: QB Energy COUEY 5-14 (N5) Pad**  
**Location #: 334963**



**Photo # 6612 Mechanical Condition – Possible leak on tank valve**



**Photo # 6613 Mechanical Condition – Possible leak on tank valve**

**Inspection/Audit Photos**  
**Location Name: QB Energy COUEY 5-14 (N5) Pad**  
**Location #: 334963**



**Photo # 6614 Mechanical Condition – Possible leak on tank valve**



**Photo # 6615 Mechanical Condition – Possible leak on tank valve**



**Inspection/Audit Photos**  
**Location Name: QB Energy COUEY 5-14 (N5) Pad**  
**Location #: 334963**



**Photo # 6616 Mechanical Condition – Possible leak on tank valve**